

2017 Site Photos

Pre-condition report and project manager's first visit



Weather
damage to
external
paintwork above
flat roofing



Weather
damage to
external
paintwork on t
side of the
building



Defective
paintwork on
interior steel
frame



Pools of water
on internal
concrete floors
due to leaks in
the building




Rear of the building being prepared for significant groundworks to dig attenuation ponds for drainage, create car park, and build gas compound



Interior before
the installation
of any stud
walling, wiring,
permanent
lighting or
stairwells



Interior of the building looking towards the front elevation prior to the refurbishing of the internal steel frame



First set of
interior stud
walls being
installed under
temporary
lighting