

Appendix A2

Schemes 2018/19

Resurfacing programme – Capital Funding (£250K + £1,250k Welsh Government funding)

	Location	Description	Identification
1.	A473 OCLP club Bryntirion	Plane out and inlay Base Course and Surface Course	Scrim/Scanner, CVI Visual Inspections, Highway Inspections
2.	a48 Stormy lane junction	Plane out and inlay Base Course and Surface Course	Scrim/Scanner, CVI Visual Inspections, Highway Inspections,
3.	B4181 Coychurch Road	Plane out and inlay Base Course and Surface Course	Scrim/Scanner, CVI Visual Inspections, Highway Inspections, Complaints (Public & Members)
4.	Brocastle avenue, waterton ind est	Plane out and inlay Base Course and Surface Course	CVI Visual Inspections, Highway Inspections, Complaints (Public & Members)
5.	B4281 Cefn road	Plane out and inlay Base Course and Surface Course	Scrim/Scanner, CVI Visual Inspections, Highway Inspections
6.	a4061 Dual from hyg r/a to penycae r/a	Plane out and inlay Base Course and Surface Course	Scrim/Scanner, CVI Visual Inspections, Highway Inspections,
7.	A48 Ewenny R/A	Plane out and inlay Base Course and Surface Course	Highway Inspections, Complaints (Public & Members)
8.	a4061 Bwlch Cattle grid up	Plane out and inlay Base Course and Surface Course	Scrim/Scanner, CVI Visual Inspections, Highway Inspections,
9.	A4061 Aber road/ogwy street, Nantymoel	Plane out and inlay Base Course and Surface Course	Scrim/Scanner, CVI Visual Inspections, Highway Inspections,
10.	station street, garth	Plane out and inlay Base Course and Surface Course	Scrim/Scanner, CVI Visual Inspections, Highway Inspections,
11.	A4093 Blackmill lights to parachute factory	Plane out and inlay Base Course and Surface Course	Scrim/Scanner, CVI Visual Inspections, Highway Inspections,
12.	Abercerdin Road,Evanstown	Plane out and inlay Base Course and Surface Course	Highway Inspections, Complaints (Public & Members)
13.	A473 Waterton r/a	Plane out and inlay Base Course and Surface Course	Highway Inspections, Complaints (Public & Members)
14.	fforrd yr eglyws, North Cornelly	Plane out and inlay Base Course and Surface Course	Highway Inspections, Complaints (Public & Members)

Appendix A2

Micro Asphalt Resurfacing – Revenue Funding (£45K)

	Location	Description	Identification
1	Woodside, Litchard	6mm Thin surfacing	Highway Inspections
2	Glen View, Litchard	6mm Thin surfacing	Highway Inspections
3	Dan y Coed, Blackmill	6mm Thin surfacing	Highway Inspections
4	Ty Merchant, Pencoed	6mm Thin surfacing	Highway Inspections

Surface Dressing Programme – Revenue Funding (£162K)

	Location	Description	Identification
1	Careg Ilwyd, Broadlands	14mm Surface Dressing	Highway Inspections
2	Ffordd tirion, broadlands	10mm Surface Dressing	Highway Inspections
3	Cefn carfan, bryncethin	14mm Surface Dressing	Scrim, Highway Inspections
4	Main road broadlands	14mm Surface Dressing	Scrim, Highway Inspections

Footway Programme (Capital funding £400k)

	Location	Description	Identification
1	PRINCESS STREET, MAESTEG	Footway renewal (PART)	Highway Inspections,
2	BLOSSE STREET, NANTYFFYLLON	Footway renewal (PART)	Highway Inspections, Condition Surveys,
3	EAST AVENUE, CEFN CRIBWR	Footway renewal (PART)	Highway Inspections, Condition Surveys,
4	WEST AVENUE, CEFN CRIBWR	Footway renewal (PART)	Highway Inspections, Condition Surveys,
5	HEOL ONNEN, NORTH CORNELLY	Footway renewal (PART)	Highway Inspections, Condition Surveys,

Appendix A2

6	WEST DRIVE, PORTHCAWL	Footway renewal (PART)	Highway Inspections, Condition Surveys,
7	BURNS CRESCENT, BRYNTIRION	Footway renewal (PART)	Highway Inspections,
8	FAIRFIELD, NORTH CORNELLY	Footway renewal (PART)	Highway Inspections, Condition Surveys,
9	DOL AFON, PENCOED	Footway renewal (PART)	Highway Inspections, Condition Surveys,
10	BRYNFFRWYD CLOSE, COYCHURCH	Footway renewal (PART)	Highway Inspections, Complaints
11	MAES Y WERN, PENCOED	Footway renewal (PART)	Highway Inspections, , Complaints
12	CHANNEL VIEW, BRACKLA	Footway renewal (PART)	Highway Inspections, Condition Surveys,
13	HEOL DEWI SANT, BETTWS	Footway renewal (PART)	Highway Inspections, Condition Surveys, Complaints
14	HILL VIEW, PONTYCYMER	Footway renewal (PART)	Highway Inspections,
15	MOIRA TERRACE, OGMORE VALE	Footway renewal (PART)	Highway Inspections,
16	KENRY STREET, EVANSTOWN	Footway renewal (PART)	Highway Inspections,

Structural programme – Capital Funding (£375K)

	Location	Description	Identification
1.	Wildmill, Bridgend (phase 2)	Parapet replacement	Structural Database, (This is the second phase of the parapet replacements and the service diversions need to be undertaken to allow the replacement)
2	Heol Richard Price, Bettws	Retaining wall replacement	Structural Database -- Failure

Appendix A2

Scour Works (Revenue Budget £150K)

	Location	Description	Identification
1.	Commercial Street, Maesteg	Repairs to scour at retaining wall	Structural inspection
2.	Charles Row, Maesteg	Repairs to scour at retaining wall	Structural inspection
3.	Llangeinor Square Culvert	Repairs and replacement of section of culvert	Structural Inspection

A4061 Frithwaun/Frithwin Bridges (Capital Scheme £2.5M over 5 years – currently YR 3)

	Location	Description	Identification
1.	A4061 Frithwaun/Frithwin Bridges	Contract documents to tender, Tender process, contract to be awarded and start on site YR 4 (2019-20)	Structural Inspection