



Highways - Inspection Job

Blocked Drain - Wed...

Inspection Details

Reference Numbers

Third Party ID 130198 **Reference ID** HF121904

Ticket Number

Customer

Customer Unknown, 194, Bridgend Road, Garth, CF34 0NA

Location Details

Incident Street Bridgend Road, Garth, Maesteg

Location Details 194

Column Number

Incident Details

Function Blocked Drain

Priority Urgent

Additional Information Blocked storm drain - Spoke to Neil

Incident Date 02/03/2016 **Created On** 02/03/2016 10:58

Inspection Details

Inspector Neil Minchington **SLA** 03/03/2016 10:57

Inspector's Notes User: R.N.M Reason for 'No Defect': no floods found

Inspection Outcome Closed - All Within Limits **Date Resolved** 02/03/2016

Inspected Defect Codes HW;DI;BD

Response Details			
Response Requested	No	Response Channel	Telephone
Response Type	Standard	Response SLA	16/03/2016 10:57
Custom Response Sent		Date Response Sent	
Status	Inactive		



Highways - Inspection Job

Drainage - Sun Nov 2...

Inspection Details

Reference Numbers

Third Party ID	Reference ID	HF122305
-----------------------	---------------------	----------

Ticket Number

Customer

Customer  Fire Service, Unknown, Unknown, Unknown, Unknown

Location Details

Incident Street  Bridgend Road, Garth, Maesteg

Location Details Garth, Maesteg

Column Number

Incident Details

Function  Drainage

Priority Urgent

Additional Information Sand Bags Requested

Incident Date	20/11/2016	Created On	21/11/2016 09:21
----------------------	------------	-------------------	------------------

Inspection Details

Inspector	 Neil Minchington	SLA	21/11/2016 06:49
------------------	--	------------	------------------

Inspector's Notes

Inspection Outcome

Date Resolved

Inspected Defect Codes

Response Details	
Response Requested No	Response Channel E-Mail
Response Type	Response SLA 05/12/2016 06:49
Custom Response Sent	Date Response Sent
Status Active	



Highways - Inspection Job

Drainage - Sun Nov 2...

Inspection Details

Reference Numbers

Third Party ID	Reference ID	HF122306
-----------------------	---------------------	----------

Ticket Number

Customer

Customer Fire Service, Pontycymmer Fire Station, Victoria Street, , CF32 8NW

Location Details

Incident Street Heol Faen, Garth, Maesteg

Location Details junction of heol faen and bridgend road.

Column Number

Incident Details

Function Drainage

Priority Urgent

Additional Information half a metre high of water

Incident Date	20/11/2016	Created On	21/11/2016 09:21
----------------------	------------	-------------------	------------------

Inspection Details

Inspector	Neil Minchington	SLA	21/11/2016 06:50
------------------	------------------	------------	------------------

Inspector's Notes

Inspection Outcome	Date Resolved
---------------------------	----------------------

Inspected Defect Codes

Response Details	
Response Requested No	Response Channel Telephone
Response Type	Response SLA 05/12/2016 06:50
Custom Response Sent	Date Response Sent
Status Active	



Highways - Inspection Job

Drainage - Sun Nov 2...

Inspection Details

Reference Numbers

Third Party ID	Reference ID	HF122317
-----------------------	---------------------	----------

Ticket Number

Customer

Customer  South Wales Fire And Rescue Service, Forest View Business Park, Llanstrisant, , CF72 8LX

Location Details

Incident Street  Heol Faen, Garth, Maesteg

Location Details number 22

Column Number

Incident Details

Function  Drainage

Priority Urgent

Additional Information severe flooding

Incident Date	20/11/2016	Created On	21/11/2016 09:21
----------------------	------------	-------------------	------------------

Inspection Details

Inspector	 Neil Minchington	SLA	21/11/2016 07:11
------------------	--	------------	------------------

Inspector's Notes

Inspection Outcome	Date Resolved
---------------------------	----------------------

Inspected Defect Codes

Response Details	
Response Requested No	Response Channel Telephone
Response Type	Response SLA 05/12/2016 07:11
Custom Response Sent	Date Response Sent
Status Active	



Highways - Inspection Job

Drainage - Sun Nov 2...

Inspection Details

Reference Numbers

Third Party ID	Reference ID	HF122322
-----------------------	---------------------	----------

Ticket Number

Customer

Customer Fire Service, Unknown, Unknown, Unknown, Unknown

Location Details

Incident Street Heol Faen, Garth, Maesteg

Location Details No. 11

Column Number

Incident Details

Function Drainage

Priority Urgent

Additional Information

Incident Date	20/11/2016	Created On	21/11/2016 09:21
----------------------	------------	-------------------	------------------

Inspection Details

Inspector	Neil Minchington	SLA	21/11/2016 07:19
------------------	------------------	------------	------------------

Inspector's Notes

Inspection Outcome

Date Resolved

Inspected Defect Codes

Response Details	
Response Requested No	Response Channel E-Mail
Response Type	Response SLA 05/12/2016 07:19
Custom Response Sent	Date Response Sent
Status Active	



Highways - Inspection Job

Drainage - Sun Nov 2...

Inspection Details

Reference Numbers

Third Party ID	Reference ID	HF122324
-----------------------	---------------------	----------

Ticket Number

Customer

Customer  South Wales Fire And Rescue Service, Forest View Business Park, Llanstrisant, , CF72 8LX

Location Details

Incident Street  Bridgend Road, Garth, Maesteg

Location Details Garth General Stores

Column Number

Incident Details

Function  Drainage

Priority Urgent

Additional Information severe flooding

Incident Date	20/11/2016	Created On	21/11/2016 09:21
----------------------	------------	-------------------	------------------

Inspection Details

Inspector	 Neil Minchington	SLA	21/11/2016 07:21
------------------	--	------------	------------------

Inspector's Notes

Inspection Outcome

Date Resolved

Inspected Defect Codes

Response Details	
Response Requested No	Response Channel Telephone
Response Type	Response SLA 05/12/2016 07:21
Custom Response Sent	Date Response Sent
Status Active	

**Highways - Inspection Job****Drainage - Sun Nov 2...****Inspection Details****Reference Numbers**

Third Party ID	Reference ID	HF122325
-----------------------	---------------------	----------

Ticket Number**Customer**

Customer	Fire Service, Unknown, Unknown, Unknown, Unknown
-----------------	--

Location Details

Incident Street	Bridgend Road, Garth, Maesteg
------------------------	-------------------------------

Location Details	No. 98
-------------------------	--------

Column Number**Incident Details**

Function	Drainage
-----------------	----------

Priority	Urgent
-----------------	--------

Additional Information	Sand bags requested
-------------------------------	---------------------

Incident Date	20/11/2016	Created On	21/11/2016 09:21
----------------------	------------	-------------------	------------------

Inspection Details

Inspector	Neil Minchington	SLA	21/11/2016 07:23
------------------	------------------	------------	------------------

Inspector's Notes	SANDBAGS DELIVERED
--------------------------	--------------------

Inspection Outcome	Closed - All Within Limits	Date Resolved	21/11/2016
---------------------------	----------------------------	----------------------	------------

Inspected Defect Codes

Response Details	
Response Requested No	Response Channel Telephone
Response Type	Response SLA 05/12/2016 07:23
Custom Response Sent	Date Response Sent
Status Inactive	



Highways - Inspection Job

Drainage - Sun Nov 2...


Inspection Details

Reference Numbers

Third Party ID	Reference ID	HF122348
-----------------------	---------------------	----------

Ticket Number

Customer

Customer  Gillian Thomas, 197, Bridgend Road, Garth, CF34 0NA

Location Details

Incident Street  Bridgend Road, Garth, Maesteg

Location Details 197

Column Number

Incident Details

Function  Drainage

Priority Urgent

Additional Information Sand bags requested as water has entered property. Also there is approx. 2ft in the garage.

Incident Date	20/11/2016	Created On	21/11/2016 09:21
----------------------	------------	-------------------	------------------

Inspection Details

Inspector	 Neil Minchington	SLA	21/11/2016 08:08
------------------	--	------------	------------------

Inspector's Notes SANDBAGS DELIVERED

Inspection Outcome	Closed - All Within Limits	Date Resolved	21/11/2016
---------------------------	----------------------------	----------------------	------------

Inspected Defect Codes

Response Details	
Response Requested No	Response Channel Telephone
Response Type	Response SLA 05/12/2016 08:08
Custom Response Sent	Date Response Sent
Status Inactive	



Highways - Inspection Job

Culvert - Mon Nov 21...

Inspection Details

Reference Numbers

Third Party ID **Reference ID** HF122424

Ticket Number

Customer

Customer  Mark Jenkins, 91, Bridgend Road, Garth, CF34 0NB

Location Details

Incident Street  Bridgend Road, Garth, Maesteg

Location Details His property

Column Number

Incident Details

Function  Culvert

Priority Urgent

Additional Information Wants to speak to a highways officer regarding the flooding in Garth this weekend and what was the cause. Mr Jenkins has currently got a claim through his house insurance.

Incident Date 21/11/2016 **Created On** 21/11/2016 10:29

Inspection Details

Inspector  Neil Minchington **SLA** 22/11/2016 10:29

Inspector's Notes This relates to Mr Jenkins making a claim, for the flooding on the weekend (19/20 Nov) However as he has made a claim BCBC cannot discuss matter with him,. Response/Report will be completed and sent to him via Insurance section.

Inspection Outcome Closed - No Action **Date Resolved** 05/12/2016

Inspected Defect Codes

Response Details	
Response Requested No	Response Channel Telephone
Response Type	Response SLA 05/12/2016 10:29
Custom Response Sent	Date Response Sent
Status Inactive	