

Novuna Vehicle Solutions

Vehicle Maintenance History

Reg No. : OU18EGC
Chassis No. : VF1JL000361073554
Radio Code :
Key Code :

Vehicle : Renault Traffic LWB Mibus Diesel LI29 Energy dCi 125 Sport Nav 9 Seater
Reg Date : 01/08/2018
MOT Date : 09/11/2023

Supplier	Date	Odo. (mi)	Description
L E Attwood T/A Allen Autos	14/08/2023	106908	Routine, PMI - 13 Weekly - Novuna Bespoke Event
L E Attwood T/A Allen Autos	14/08/2023	106908	Adjust, Column - Adjust, Steering wheel - centralise
L E Attwood T/A Allen Autos	14/08/2023	106908	Remove & Refit, Wash/Wipe Systems - Remove & Refit, Windscreen wiper - blade/s
L E Attwood T/A Allen Autos	14/08/2023	106908	Remove & Refit, Brake Pedal - Remove & Refit, Brake pedal rubber
L E Attwood T/A Allen Autos	14/08/2023	106908	Routine, Other Unspecified Work - Routine, Brake Efficiency Test
L E Attwood T/A Allen Autos	14/08/2023	106908	Remove & Refit, Disc - Remove & Refit, Disc (incl. pads) - rear (pair)
L E Attwood T/A Allen Autos	14/08/2023	106908	Remove & Refit, Bumpers - Remove & Refit, Bumper assy - rear
L E Attwood T/A Allen Autos	14/08/2023	106908	Routine, Other Unspecified Work - Routine, Unscheduled Labour
L E Attwood T/A Allen Autos	14/08/2023	106908	Remove & Refit, Switches - Remove & Refit, Switch - electric window (front door) right
L E Attwood T/A Allen Autos	14/08/2023	106908	Remove & Refit, Gear Lever - Remove & Refit, Gear lever knob
L E Attwood T/A Allen Autos	14/08/2023	106908	Remove & Refit, Battery - Remove & Refit, Charging circuit - battery
L E Attwood T/A Allen Autos	14/08/2023	106908	Remove & Refit, Rear Crossmember/Sub-Frame - Remove & Refit, Crossmember, axle tube c
L E Attwood T/A Allen Autos	14/08/2023	106908	Check & Adjust, Front And Rear Alignment - Check & Adjust, Wheel Alignment - front/rear
750 - STA Michelin	21/07/2023		Removed Tyre, Position: B 4, 2156017VANCO200, CONTINENTAL, Removal Reason: Tyre -
750 - STA Michelin	21/07/2023		New Tyre, Position: B 4, 3RD4450410, CONTINENTAL, Tread: 9mm, Location: Rapid Respon
750 - STA Michelin	21/07/2023		TUBELESS VALVE FITTED - CAR, Position: B 4, Location: Rapid Response Mobile-NTA Mc
750 - STA Michelin	21/07/2023		SCRAP DISPOSAL CAR VAN 4X4, Position: B 4, Location: Rapid Response Mobile-NTA Mc
750 - STA Michelin	21/07/2023		WHEEL BALANCE-CAR(A), Position: B 4, Location: Rapid Response Mobile-NTA Mobile
750 - STA Michelin	21/07/2023		R/RESP RSIDE VAN OUT OF HOURS, Location: Rapid Response Mobile-NTA Mobile
Theoco Limited	22/06/2023	104707	Check, Checks - Check, Investigate & Report
Theoco Limited	22/06/2023	104707	Remove & Refit, Clutch Unit/Cable - Remove & Refit, Clutch - assy
Theoco Limited	22/06/2023	104707	Remove & Refit, Cooling System - Remove & Refit, Cooling system - drain and refill

Novuna Vehicle Solutions

Vehicle Maintenance History

Supplier	Date	Odo. (mi)	Description
Theoco Limited	22/06/2023	104707	Check & Adjust, Front And Rear Alignment - Check & Adjust, Wheel Alignment - front/rear
Theoco Limited	22/06/2023	104707	Remove & Refit, Exhaust Gas Analysis - Remove & Refit, Exhaust gas recirculation (EGR) val
Theoco Limited	22/06/2023	104707	Remove & Refit, Drive And Prop-Shafts - Remove & Refit, Front drive shaft assy (open shafts)
Theoco Limited	22/06/2023	104707	Remove & Refit, Drive And Prop-Shafts - Remove & Refit, Front drive shaft assy (open shafts)
Theoco Limited	22/06/2023	104707	Routine, PMI - 13 Weekly - Novuna Bespoke Event
Theoco Limited	22/06/2023	104707	Remove & Refit, Fusebox - Remove & Refit, Fusebox
RAC Motoring ***MAINT***	06/06/2023	102518	Routine, Other Unspecified Work - Routine, Breakdown
750 - STA Michelin	17/04/2023	102518	Removed Tyre, Position: A 2, 2156017UN3R, UNIROYAL, Removal Reason: Tyre - Sidewall C
750 - STA Michelin	17/04/2023	102518	New Tyre, Position: A 2, 2156017UN3R, UNIROYAL, Tread: 9mm, Location: Rapid Response
750 - STA Michelin	17/04/2023	102518	SCRAP DISPOSAL CAR VAN 4X4, Position: A 2, Location: Rapid Response Mobile-MFS R8
750 - STA Michelin	17/04/2023	102518	TUBELESS VALVE FITTED - CAR, Position: A 2, Location: Rapid Response Mobile-MFS R8
750 - STA Michelin	17/04/2023	102518	WHEEL BALANCE-CAR(A), Position: A 2, Location: Rapid Response Mobile-MFS R&J Strang
750 - STA Michelin	17/04/2023	102518	R/RESP R/SIDE VAN NORMAL HRS, Location: Rapid Response Mobile-MFS R&J Strang Tyr
Ferno UK Ltd	14/03/2023	98487	Routine, Winch Insp - Annual - Novuna Bespoke Event
Ferno UK Ltd	14/03/2023	98487	Routine, Wheelchair Ramp Insp - Annual - Novuna Bespoke Event
Ferno UK Ltd	14/03/2023	98487	Routine, Seat Belt Insp - Annual - Novuna Bespoke Event
Ferno UK Ltd	14/03/2023	98487	Routine, Other Unspecified Work - Routine, Unscheduled Labour
Theoco Limited	30/01/2023	98487	Routine, PMI - 13 Weekly - Novuna Bespoke Event
Theoco Limited	26/01/2023	97537	Remove & Refit, Other Unspecified Work - Remove & Refit, Step Assembly
Theoco Limited	26/01/2023	97537	Remove & Refit, Other Unspecified Work - Remove & Refit, Step Assembly
L E Attwood T/A Allen Autos	08/11/2022	95915	Routine, PMI - 13 Weekly - Novuna Bespoke Event
L E Attwood T/A Allen Autos	08/11/2022	95915	Routine, Mot Test - Routine, Brake Test
L E Attwood T/A Allen Autos	08/11/2022	95915	Routine, MOT - Class IV (9 - 12 Passenger Seats)
L E Attwood T/A Allen Autos	08/11/2022	95915	Routine, 100000 mls/kms Service - 2014/- Traffic III (25,000 miles/2 year intervals)
L E Attwood T/A Allen Autos	08/11/2022	95915	Remove & Refit, Linings (Pads & Shoes) - Remove & Refit, Pads - front (axle set)

Novuna Vehicle Solutions

Vehicle Maintenance History

Supplier	Date	Odo. (mi)	Description
L E Attwood T/A Allen Autos	08/11/2022	95915	Remove & Refit, Bumpers - Remove & Refit, Bumper - finisher (front)
Ferno UK Ltd	21/09/2022	90704	Routine, Winch Insp - Annual - Novuna Bespoke Event
Ferno UK Ltd	21/09/2022	90704	Routine, Wheelchair Ramp Insp - Annual - Novuna Bespoke Event
Ferno UK Ltd	21/09/2022	90704	Routine, Seat Belt Insp - Annual - Novuna Bespoke Event
Ferno UK Ltd	21/09/2022	90704	Routine, Other Unspecified Work - Routine, Unscheduled Labour
750 - STA Michelin	12/08/2022	89275	Removed Tyre, Position: B 1, 2156017ECODRIVE, DUNLOP, Removal Reason: Tyre - Tread
750 - STA Michelin	12/08/2022	89275	New Tyre, Position: B 1, 2156017T178879, BUDGET, Tread: 9mm, Location: Rapid Response
750 - STA Michelin	12/08/2022	89275	TUBELESS VALVE FITTED - CAR, Position: B 1, Location: Rapid Response Mobile-Aone Ty
750 - STA Michelin	12/08/2022	89275	SCRAP DISPOSAL CAR VAN 4X4, Position: B 1, Location: Rapid Response Mobile-Aone Ty
750 - STA Michelin	12/08/2022	89275	WHEEL BALANCE-CAR(A), Position: B 1, Location: Rapid Response Mobile-Aone Tyres Hear
750 - STA Michelin	12/08/2022	89275	R/RESP R/SIDE VAN NORMAL HRS, Location: Rapid Response Mobile-Aone Tyres Head Of
L E Attwood T/A Allen Autos	28/07/2022	90704	Routine, PMI - 13 Weekly - Novuna Bespoke Event
L E Attwood T/A Allen Autos	28/07/2022	90704	Routine, Other Unspecified Work - Routine, Brake Efficiency Test
L E Attwood T/A Allen Autos	28/07/2022	90704	Routine, Service - 30,000/24month - Novuna Bespoke Event
L E Attwood T/A Allen Autos	12/05/2022	85739	Routine, 4 year Service - 2014/- Traffic III (25,000 miles/2 year intervals)
L E Attwood T/A Allen Autos	12/05/2022	85739	Routine, Other Unspecified Work - Routine, Unscheduled Labour
L E Attwood T/A Allen Autos	12/05/2022	85739	Remove & Refit, Hoses - Remove & Refit, Hose (Brake) - front (one) right
L E Attwood T/A Allen Autos	12/05/2022	85739	Remove & Refit, Hoses - Remove & Refit, Hose (Brake) - front (one) left
L E Attwood T/A Allen Autos	12/05/2022	85739	Remove & Refit, Hoses - Remove & Refit, Hose (Brake) - rear left
L E Attwood T/A Allen Autos	12/05/2022	85739	Remove & Refit, Wash/Wipe Systems - Remove & Refit, Windscreen wiper - blade/s
L E Attwood T/A Allen Autos	12/05/2022	85739	Remove & Refit, Lamps - Remove & Refit, Lamps exterior - foglamp/driving lamp assy right
L E Attwood T/A Allen Autos	12/05/2022	85739	Remove & Refit, Front Shock Absorber - Remove & Refit, Shock absorber/damper (one) (Fron
L E Attwood T/A Allen Autos	12/05/2022	85739	Remove & Refit, All Exhaust Components - Remove & Refit, Exhaust heat shield
L E Attwood T/A Allen Autos	12/05/2022	85739	Remove & Refit, Mountings - Remove & Refit, Mounting - Gearbox (manual)
L E Attwood T/A Allen Autos	12/05/2022	85739	Remove & Refit, Bumpers - Remove & Refit, Bumper assy - rear

Vehicle Maintenance History

Supplier	Date	Odo. (mi)	Description
L E Attwood T/A Allen Autos	12/05/2022	85739	Remove & Refit, Engine Assembly - Remove & Refit, Undertray - Engine
L E Attwood T/A Allen Autos	12/05/2022	85739	Remove & Refit, Linings (Pads & Shoes) - Remove & Refit, Pads - rear (axle set)
Ferno UK Ltd	20/04/2022	84674	Routine, Winch Service - 6 Monthly - Novuna Bespoke Event
Ferno UK Ltd	20/04/2022	84674	Routine, Wheelchair Ramp Insp - Annual - Novuna Bespoke Event
Ferno UK Ltd	20/04/2022	84674	Routine, Seat Belt Insp - Annual - Novuna Bespoke Event
Ferno UK Ltd	20/04/2022	84674	Routine, Other Unspecified Work - Routine, Unscheduled Labour
Ferno UK Ltd	20/04/2022	84674	Routine, Other Unspecified Work - Routine, Unscheduled Labour
750 - STA Michelin	23/03/2022	82189	Removed Tyre, Position: B 1, 2156017ECODRIVE, DUNLOP, Removal Reason: Tyre - Tread
750 - STA Michelin	23/03/2022	82189	New Tyre, Position: B 1, 2156017T179599, BUDGET, Tread: 9mm, Location: Rapid Response
750 - STA Michelin	23/03/2022	82189	TUBELESS VALVE FITTED - CAR, Position: B 1, Location: Rapid Response Mobile-Aone Ty
750 - STA Michelin	23/03/2022	82189	WHEEL BALANCE-CAR(A), Position: B 1, Location: Rapid Response Mobile-Aone Tyres Hear
750 - STA Michelin	23/03/2022	82189	SCRAP DISPOSAL CAR VAN 4X4, Position: B 1, Location: Rapid Response Mobile-Aone Ty
750 - STA Michelin	23/03/2022	82189	R/RESP RSIDE VAN OUT OF HOURS, Location: Rapid Response Mobile-Aone Tyres Head C
Double 4 Ltd	17/02/2022	81353	Routine, Mot Test - Routine, Brake Test
Double 4 Ltd	17/02/2022	81353	Routine, PMI - 13 Weekly - HCVS Bespoke Event
Double 4 Ltd	17/02/2022	81353	Remove & Refit, Track Rod - Remove & Refit, Track rod - outer left
Double 4 Ltd	17/02/2022	81353	Remove & Refit, Track Rod - Remove & Refit, Track rod - outer right
Double 4 Ltd	17/02/2022	81353	Remove & Refit, Brake Pedal - Remove & Refit, Brake pedal rubber
Double 4 Ltd	17/02/2022	81353	Check & Adjust, Front And Rear Alignment - Check & Adjust, Wheel Alignment - front/rear
Double 4 Ltd	17/02/2022	81353	Routine, Movement - Routine, Movement - Miscellaneous
Double 4 Ltd	10/01/2022	79561	Check, Checks - Check, Investigate & Report
Double 4 Ltd	10/01/2022	79561	Remove & Refit, Engine Assembly - Remove & Refit, Auxiliary drive belt tensioner
Double 4 Ltd	10/01/2022	79561	Remove & Refit, Crankshaft - Remove & Refit, Crankshaft pulley
RAC Motoring ***MAINT***	22/12/2021		Routine, Other Unspecified Work - Routine, Breakdown
RAC Motoring ***MAINT***	22/12/2021		Routine, Other Unspecified Work - Routine, Mechanical Recovery

Novuna Vehicle Solutions

Vehicle Maintenance History

Supplier	Date	Odo. (mi)	Description
Double 4 Ltd	04/11/2021	76623	Routine, PMI - 13 Weekly - HCVS Bespoke Event
Double 4 Ltd	04/11/2021	76623	Routine, Mot Test - Routine, Brake Test
Double 4 Ltd	04/11/2021	76623	Routine, MOT - Pre Insp - Minibus - HCVS Bespoke Event
Double 4 Ltd	04/11/2021	76623	Check & Adjust, Lamps - Check & Adjust, Headlamp alignment
Double 4 Ltd	04/11/2021	76623	Routine, Mot Test - Routine, Present to Test Centre
Double 4 Ltd	04/11/2021	76623	Routine, MOT - Class V (13 - 16 Passenger Seats)
Double 4 Ltd	04/11/2021	76623	Remove & Refit, Rear Shock Absorber - Remove & Refit, Shock absorber/damper (pair) (Rear
Double 4 Ltd	04/11/2021	76623	Routine, 75000 mls/kms Service - 2014/- Traffic III (25,000 miles/2 year intervals)
Ferno UK Ltd	26/10/2021	76269	Routine, Winch Service - 6 Monthly - HCVS Bespoke Event
Ferno UK Ltd	26/10/2021	76269	Routine, Wheelchair Ramp Insp - Annual - HCVS Bespoke Event
Ferno UK Ltd	26/10/2021	76269	Routine, Seat Belt Insp - Annual - HCVS Bespoke Event
Double 4 Ltd	27/09/2021	74385	Remove & Refit, Clutch Unit/Cable - Remove & Refit, Clutch - assy
Double 4 Ltd	27/09/2021	74385	Remove & Refit, Flywheel - Remove & Refit, Flywheel/drive plate
Double 4 Ltd	22/09/2021	74382	Routine, Mot Test - Routine, Brake Test
Double 4 Ltd	22/09/2021	74382	Routine, PMI - 13 Weekly - HCVS Bespoke Event
Double 4 Ltd	17/05/2021	72205	Routine, PMI - 13 Weekly - HCVS Bespoke Event
Double 4 Ltd	17/05/2021	72205	Routine, Mot Test - Routine, Brake Test
Double 4 Ltd	17/05/2021	72205	Remove & Refit, Track Rod End - Remove & Refit, Ball joint/track rod ends
Double 4 Ltd	17/05/2021	72205	Remove & Refit, Disc - Remove & Refit, Disc - front (pair)
Double 4 Ltd	17/05/2021	72205	Remove & Refit, Disc - Remove & Refit, Disc - rear (pair)
Double 4 Ltd	17/05/2021	72205	Routine, Mot Test - Routine, Brake Test
Double 4 Ltd	17/05/2021	72205	Check, Checks - Check, Investigate & Report
Double 4 Ltd	17/05/2021	72205	Remove & Refit, Cab - Remove & Refit, Cab Repairs
Double 4 Ltd	17/05/2021	72205	Remove & Refit, Cab - Remove & Refit, Cab Repairs
Double 4 Ltd	17/05/2021	72205	Remove & Refit, Calipers - Remove & Refit, Caliper - rear (one) right

Vehicle Maintenance History

Supplier	Date	Odo. (mi)	Description
Double 4 Ltd	17/05/2021	72205	Remove & Refit, Calipers - Remove & Refit, Calliper - rear (one) left
750 - STA Michelin	10/05/2021	72205	Removed Tyre, Position: A 3, 2156017VANCO200, CONTINENTAL, Removal Reason: Tyre -
750 - STA Michelin	10/05/2021	72205	New Tyre, Position: A 3, 2156017AGICRSCL, MICHELIN, Tread: 8mm, Location: Standard Mc
750 - STA Michelin	10/05/2021	72205	TUBELESS VALVE FITTED - CAR, Position: A 3, Location: Standard Mobile-Halfords Tyres
750 - STA Michelin	10/05/2021	72205	SCRAP DISPOSAL CAR VAN 4X4, Position: A 3, Location: Standard Mobile-Halfords Tyres
750 - STA Michelin	10/05/2021	72205	WHEEL BALANCE-CAR(A), Position: A 3, Location: Standard Mobile-Halfords Tyres on the D
750 - STA Michelin	19/04/2021	71382	Removed Tyre, Position: A 2, 2156017CT1R, CONTINENTAL, Removal Reason: Tyre - Run F
750 - STA Michelin	19/04/2021	71382	New Tyre, Position: A 2, 2156017CT1R, CONTINENTAL, Tread: 10mm, Location: Rapid Resp
750 - STA Michelin	19/04/2021	71382	TUBELESS VALVE FITTED - CAR, Position: A 2, Location: Rapid Response Mobile-Tyretrax
750 - STA Michelin	19/04/2021	71382	SCRAP DISPOSAL CAR VAN 4X4, Position: A 2, Location: Rapid Response Mobile-Tyretrax
750 - STA Michelin	19/04/2021	71382	WHEEL BALANCE-CAR(A), Position: A 2, Location: Rapid Response Mobile-Tyretrax
750 - STA Michelin	19/04/2021	71382	R/RESP R/SIDE VAN NORMAL HRS, Location: Rapid Response Mobile-Tyretrax
Double 4 Ltd	24/02/2021	68280	Routine, 75000 mls/kms Service - 2014/- Traffic III (25,000 miles/2 year intervals)
Double 4 Ltd	24/02/2021	68280	Check, Checks - Check, Investigate & Report
Double 4 Ltd	05/02/2021	68273	Routine, Movement - Routine, Movement - Collection & Delivery
Double 4 Ltd	05/02/2021	68273	Routine, Mot Test - Routine, Brake Test
Double 4 Ltd	05/02/2021	68273	Routine, PMI - 13 Weekly - HCVS Bespoke Event
Double 4 Ltd	05/02/2021	68273	Remove & Refit, Cab - Remove & Refit, Cab Repairs
Double 4 Ltd	05/02/2021	68273	Remove & Refit, Oil Lubrication - Remove & Refit, Oil filler cap
Double 4 Ltd	05/02/2021	68273	Check, Checks - Check, Investigate & Report
Ferno UK Ltd	23/12/2020	66677	Routine, Winch Service - 6 Monthly - HCVS Bespoke Event
Ferno UK Ltd	23/12/2020	66677	Routine, Wheelchair Ramp Insp - Annual - HCVS Bespoke Event
Ferno UK Ltd	23/12/2020	66677	Routine, Seat Belt Insp - Annual - HCVS Bespoke Event
Ferno UK Ltd	23/12/2020	66677	Remove & Refit, Safety Equipment - Remove & Refit, Fire extinguisher cartridge
Ferno UK Ltd	23/12/2020	66677	Routine, Other Unspecified Work - Routine, Unscheduled Labour

Novuna Vehicle Solutions

Vehicle Maintenance History

Supplier	Date	Odo. (mi)	Description
Vanguard Fleet Services Ltd ***MAINT***	12/11/2020	64717	Check, Checks - Check, Investigate & Report
Double 4 Ltd	10/11/2020	64075	Routine, MOT - Pre Insp - Minibus - HCVS Bespoke Event
Double 4 Ltd	10/11/2020	64075	Routine, PMI - 13 Weekly - HCVS Bespoke Event
Double 4 Ltd	10/11/2020	64075	Routine, Mot Test - Routine, Brake Test
Double 4 Ltd	10/11/2020	64075	Check & Adjust, Lamps - Check & Adjust, Headlamp alignment
Double 4 Ltd	10/11/2020	64075	Routine, MOT - Class IV (9 - 12 Passenger Seats)
Double 4 Ltd	10/11/2020	64075	Routine, Mot Test - Routine, Present to Test Centre
Double 4 Ltd	10/11/2020	64075	Remove & Refit, Lower Panel - Remove & Refit, Lower panel - rear
Double 4 Ltd	10/11/2020	64075	Remove & Refit, Engine Assembly - Remove & Refit, Auxiliary drive belt tensioner
Double 4 Ltd	10/11/2020	64075	Remove & Refit, Disc - Remove & Refit, Disc - rear (pair)
Double 4 Ltd	10/11/2020	64075	Remove & Refit, Seats - Remove & Refit, Seat - armrest (rear) (centre)
Double 4 Ltd	10/11/2020	64075	Check, Checks - Check, Investigate & Report
Double 4 Ltd	10/11/2020	64075	Check, Checks - Check, Investigate & Report
Double 4 Ltd	10/11/2020	64075	Remove & Refit, Seat Belts - Remove & Refit, Seat belt - rear (side) (complete with buckle)
Double 4 Ltd	14/08/2020	59796	Routine, PMI - 13 wks (Safety Inspection) - Hitachi Bespoke Inspection or Test
Double 4 Ltd	14/08/2020	59796	Routine, Mot Test - Routine, Brake Test
Double 4 Ltd	14/08/2020	59796	Routine, Service - 30,000/24month - HCVS Bespoke Event
Renault London West	03/08/2020	59316	Routine, Other Unspecified Work - Routine, Unscheduled Labour
R S Recovery Ltd	15/07/2020	59316	Routine, Other Unspecified Work - Routine, Call Out Charge
R S Recovery Ltd	15/07/2020	59316	Routine, Other Unspecified Work - Routine, Recovery/Storage Fee
Ferno UK Ltd	08/07/2020	58055	Routine, Winch Inspection
Ferno UK Ltd	08/07/2020	58055	Routine, Wheel Chair Ramp Inspection
Ferno UK Ltd	08/07/2020	58055	Routine, Seat Belt Inspection
Double 4 Ltd	15/05/2020	53516	Mot Test - Routine, Brake Test
Double 4 Ltd	15/05/2020	53516	Wash/Wipe Systems - Remove & Refit, Windscreen wiper - blade/s

Novuna Vehicle Solutions

Vehicle Maintenance History

Supplier	Date	Odo. (mi)	Description
Double 4 Ltd	15/05/2020	53516	Disc - Remove & Refit, Disc - rear (pair)
Double 4 Ltd	15/05/2020	53516	Movement - Routine, Movement - Engineer Waiting Time
Double 4 Ltd	15/05/2020	53516	Mot Test - Routine, Brake Test
Double 4 Ltd	15/05/2020	53516	PMI - 13 wks (Safety Inspection) - Hitachi Bespoke Inspection or Test
Double 4 Ltd	15/05/2020	53516	Movement - Routine, Movement - Collection & Delivery
Renault London West	20/02/2020	46044	Brake Pedal - Remove & Refit, Brake pedal rubber
Renault London West	20/02/2020	46044	Interval Service
Double 4 Ltd	13/02/2020	45459	PMI - 13 wks (Safety Inspection) - Hitachi Bespoke Inspection or Test
Double 4 Ltd	13/02/2020	45459	Mot Test - Routine, Brake Test
Double 4 Ltd	13/02/2020	45459	Movement - Routine, Movement - Collection & Delivery
Oughtred & Harrison (Facilities) Ltd ****MAINT****	13/02/2020		Check Investigate & Report
Oughtred & Harrison (Facilities) Ltd ****MAINT****	13/02/2020		Remove & Refit Step Assy
Ferno UK Ltd	11/02/2020	46006	Other Unspecified Work - Routine, Unscheduled Labour
Ferno UK Ltd	11/02/2020	46006	Safety Inspection
Ferno UK Ltd	11/02/2020	46006	Winch Inspection 6 Monthly - Hitachi Bespoke Inspection or Test
Internal Dr Charges To Maintenance	24/01/2020	46205	MANUFACTURER - Downtime Claim
Double 4 Ltd	27/12/2019	41815	Movement - Routine, Movement - Collection & Delivery
Double 4 Ltd	27/12/2019	41815	Linings (Pads & Shoes) - Remove & Refit, Pads - rear (axle set)
Double 4 Ltd	27/12/2019	41815	Disc - Remove & Refit, Disc - front (pair)
Double 4 Ltd	27/12/2019	41815	Checks - Check, Investigate & Report
Double 4 Ltd	27/12/2019	41815	Front And Rear Alignment - Check & Adjust, Wheel Alignment - front/rea
R S Recovery Ltd	13/12/2019		Other Unspecified Work - Routine, Roadside Assistance
R S Recovery Ltd	13/12/2019		Movement - Routine, Movement - Miscellaneous
R S Recovery Ltd	13/12/2019		Other Unspecified Work - Routine, Call Out Charge
751 - F29 PPV Direct Tyre Management**INTERNAL ACC	11/12/2019	41817	Breakdown - Tyres,NSR

Novuna Vehicle Solutions

Vehicle Maintenance History

Supplier	Date	Odo. (mi)	Description
751 - F29 PPV Direct Tyre Management**INTERNAL ACC	11/12/2019	41817	Tyres - Environmental Disposal,OSF
751 - F29 PPV Direct Tyre Management**INTERNAL ACC	11/12/2019	41817	Tyres - Environmental Disposal,NSF
751 - F29 PPV Direct Tyre Management**INTERNAL ACC	11/12/2019	41817	Tyre worn out, OSF 0mm left, fit 2156017CONT1107T
751 - F29 PPV Direct Tyre Management**INTERNAL ACC	11/12/2019	41817	Tyre worn out, NSF 0mm left, fit 2156017CONT1107T
Oughtred & Harrison (Facilities) Ltd ***MAINT***	11/12/2019		Step Assy
Double 4 Ltd	08/11/2019	38137	100000 mls/kms Service - 2014/- Traffic III (25,000 miles/2 year inter
Double 4 Ltd	08/11/2019	38137	Movement - Routine, Movement - Collection & Delivery
Double 4 Ltd	08/11/2019	38937	Mot Test - Routine, Brake Test
Double 4 Ltd	08/11/2019	38937	PMI - 13 wks (Safety Inspection) - Hitachi Bespoke Inspection or Test
Vanguard Fleet Services Ltd ***MAINT***	26/09/2019	33657	Checks - Check, Investigate & Report
Royal Mail North London Workshop	07/08/2019	27732	PMI - 13 wks (Safety Inspection) - Hitachi Bespoke Inspection or Test
Felgate Motor Co Ltd	16/07/2019	25281	Linings (Pads & Shoes) - Remove & Refit, Pads - rear (axle set)
Felgate Motor Co Ltd	16/07/2019	25281	Linings (Pads & Shoes) - Remove & Refit, Pads - front (axle set)
Felgate Motor Co Ltd	16/07/2019	25281	AdBlue - Remove & Refit, AdBlue fluid
Felgate Motor Co Ltd	16/07/2019	25281	25000 mls/kms Service - 2014/- Traffic III (25,000 miles/2 year interv
Ferno UK Ltd	03/07/2019	20854	Other Unspecified Work - Routine, Check/Test
Ferno UK Ltd	03/07/2019	20854	Seat Belt Inspection
Ferno UK Ltd	12/06/2019	20854	Other Unspecified Work - Routine, Unscheduled Labour
Ferno UK Ltd	12/06/2019	20854	Winch Inspection 6 Monthly - Hitachi Bespoke Inspection or Test
Ferno UK Ltd	12/06/2019	20854	Other Unspecified Work - Routine, Other Unspecified Repair
Ferno UK Ltd	12/06/2019	20854	Winch Inspection 6 Monthly - Hitachi Bespoke Inspection or Test
Ferno UK Ltd	12/06/2019	20854	Wheel Chair Ramp Insp/Serv - Hitachi Bespoke Inspection or Test
Royal Mail North London Workshop	14/05/2019	16931	MOT - Class IV Cars (Up To 8 Passenger Seats)
Royal Mail North London Workshop	14/05/2019	16931	Checks - Check, Pre-check - Government Vehicle Test
Royal Mail North London Workshop	14/05/2019	16931	PMI - 13 wks (Safety Inspection) - Hitachi Bespoke Inspection or Test

Novuna Vehicle Solutions

Vehicle Maintenance History

Supplier	Date	Odo. (mi)	Description
Alfa Tail Lifts	11/03/2019	10684	MFL WAV Side Step Repair
Alfa Tail Lifts	11/03/2019	10684	Checks - Check, MFL WAV Side Step Repair
Alfa Tail Lifts	11/03/2019	10684	Movement - Routine, Non-Standard Vehicle Movement
D & D Autos	06/02/2019	10697	AdBlue - Remove & Refit, AdBlue fluid
D & D Autos	06/02/2019	10697	PMI - 13 wks (Safety Inspection) - Hitachi Bespoke Inspection or Test
Alfa Tail Lifts	30/01/2019	10684	Other Unspecified Work - Add once only, Plant / Equipment - Oil/Lube
Alfa Tail Lifts	30/01/2019	10684	Winch Inspection 6 Monthly - Hitachi Bespoke Inspection or Test
Alfa Tail Lifts	21/12/2018	8777	Checks - Check, MFL WAV Side Step Repair
Alfa Tail Lifts	21/12/2018	8777	Movement - Routine, Movement - Engineer Onsite
Alfa Tail Lifts	18/12/2018	8524	Checks - Check, Investigate & Report
Alfa Tail Lifts	18/12/2018	8524	Movement - Routine, Non-Standard Vehicle Movement
Driveline	07/12/2018	7841	25000 mls/kms Service - 2014/- Traffic III (25,000 miles/2 year interv
D & D Autos	05/12/2018	7714	Checks - Check, Investigate & Report
D & D Autos	07/11/2018	5336	PMI - 13 wks (Safety Inspection) - Hitachi Bespoke Inspection or Test